GO WITH THE FLOW.

TECALEMIT

QUICK GUIDE

SUPERBOX

EXPORTING FROM HD MANAGER TO USB FOR SUPERBOX

www.tecalemitUSA.com I support@tecalemitUSA.com

Tel +1-281-446-7300 I Fax 281-619-5613

EXPORTING FROM HD MANAGER TO USB FOR SUPERBOX:

- Open your HD Manager Software.
- Click on the Masterdata tab.
- Click on Export in the green bar.
- Select the Fuel Terminal you want to export to.
- Select "HDA-5 eco/HDA pro".
- Click Export.
- File explorer will come up with the "DATAIN" file and prompt you to save.
- Save the file directly on the USB stick.